

C² WASH

C2 Wash™ is a proprietary concentrated cleaner designed specifically for newly installed concrete floors. C2 Wash™ removes laitance and residual surface salts often related to blanket curing. These contaminants, when left on the floor surface, can interfere with penetration, bond and effectiveness of hardener/densifiers and other flooring treatments. Use C2 Wash™ immediately after removing curing blankets, or within 3-7 days of installation, or any time thereafter for fast, easy removal of laitance and surface salts.

ADVANTAGES

- Effective in removing salts from freshly placed concrete.
- Ideal for auto-scrubbing machines.
- Concentrated for easy transport and storage
- Planet safe, water-based, contains no solvents, non-toxic, no odor, non-flammable and fast drying.
- Easy to apply.

Limitations

- Not made to remove some embedded stains.

TYPICAL TECHNICAL DATA

FORM	Clear liquid
SPECIFIC GRAVITY	1.29
pH	4.8
WT/GAL	10.83 lbs
ACTIVE CONTENT	NA
TOTAL SOLIDS	NA
VOC CONTENT	0%
FLASH POINT	>93°C (200°F)
FREEZE POINT	NA
SHELF LIFE	2 years in tightly sealed, unopened container

REGULATORY COMPLIANCE

VOC Compliance

C² Wash is compliant with the US Environmental Protection Agency's AIM VOC regulations.

Contact us at sales@cretecolors.com for compliance questions with individual country regulations.

SAFETY INFORMATION

Always read full label and SDS for precautionary instructions before use. Use appropriate safety equipment and job site controls during application and handling.

24-Hour Emergency Information:
INFOTRAC at +1-352-323-3500



PREPARATION

Protect people, vehicles, property, plants, metal, all non-masonry and acid-sensitive surfaces from contact with product, rinse residue, fumes and wind drift. Protect or divert auto and foot traffic. Clean when traffic is at a minimum.

Surface & Air Temperatures

Do not apply at air and surface temperatures below 4°C (40°F). Best air and surface temperatures for cleaning are 10°C (50°F) or above. Cleaning effectiveness is reduced when surface and air temperature fall below 10°C (50°F). Allow masonry to thaw if freezing conditions exist before application.

Packaging

3.5L, 20L or 200L containers

Equipment

For best results use automatic scrubber or cleaning mop or low-pressure, pump-up sprayer.

Storage & Handling

Store in cool and dry place. Maintain temperature of 4-38°C (40-100°F), protect from extreme temperatures and keep from freezing. Do not double-stack pallets. Published shelf life assumes upright storage of factory-sealed container in a cool dry place. Do not alter or mix with other chemicals. Thaw and mix well before using and always seal container after dispensing. Dispose of unused product and container in accordance with local regulations. Do not reuse container or remove labels. Keep this and other chemicals out of the reach of children.

APPLICATION

Read "Preparation" and the Safety Data Sheet before use.

ALWAYS TEST a small area of each surface to confirm suitability, coverage rate and desired results before beginning overall application. Test with the same equipment, recommended surface preparation and application procedures planned for general application. Let surface dry thoroughly before inspection.

Dilution

Dilute 1 part C² Wash with 4 parts of fresh water. Mix well. Always pour cold water into an empty bucket first, and then carefully add the cleaner. When applying with an auto scrubber, add water to tank before adding product.

Typical Coverage Rates

Coverage rate will vary with concrete quality and porosity. Always test. Typical coverage is:

- 15 – 30 m² per Liter
- 600 – 1200 ft² per US gallon

Auto Scrubber

After removing the curing blankets, scrub and vacuum area with clean water.

- Apply C² Wash while scrubbing with squeegee upwards. Limit application of C² Wash to an area that can be cleaned and scrubbed within 10-15 minutes.
- Scrub while removing C² Wash from the floor with vacuuming.
- Rinse with clean water.

Mop or Spray Application

After removing curing blankets, rinse area with clean water.

- Apply diluted C² Wash with a clean mop or sprayer.
- Let cleaner dwell for 15 minutes. Do not allow to dry.
- Scrub with deck brush or stiff bristle broom.
- Mop up spent cleaner.
- Rinse with clean water and mop.

Cleanup

Clean tools and equipment with soap and water.

BEST PRACTICES

All loose construction debris and foreign materials from surfaces to be treated needs to be removed using a dry broom.

Do not apply C² products on surfaces which are frozen, dirty or retain standing water. Application with an auto scrubber is recommended, particularly on large floors. Using a second auto scrubber for rinsing will increase production.

Average settling time for C² Wash is 15 minutes. Slightly longer or shorter settles may be required based on concrete porosity, and the level of laitance and surface salts to be removed.



WARRANTY

The information and recommendations made are based on our own research and the research of others, and are believed to be accurate. However, no guarantee of their accuracy is made because we cannot cover every possible application of our products, nor anticipate every variation encountered in masonry surfaces, job conditions and methods used. The purchasers shall make their own tests to determine the suitability of such products for a particular purpose.

Crete Colors International warrants this product to be free from defects. *Where permitted by law, Crete Colors makes no other warranties with respect to this product, express or implied, including without limitation the implied warranties of merchantability or fitness for particular purpose.* The purchaser shall be responsible to make his own tests to determine the suitability of this product for his particular purpose. Crete Colors International's liability shall be limited in all events to supplying sufficient product to re-treat the specific areas to which defective product has been applied. Acceptance and use of this product absolves Crete Colors from any other liability, from whatever source, including liability for incidental, consequential or resultant damages whether due to breach of warranty, negligence or strict liability.

This warranty may not be modified or extended by representatives of Crete Colors, its distributors or dealers.

CUSTOMER CARE

Factory personnel are available for product, environment and job-safety assistance with no obligation. Email us at sales@cretecolors.com for technical support.

Factory-trained representatives are established in countries around the world. Contact us or visit our web site at www.cretecolors.com, for the name of the Crete Colors representative in your area.